

FIG.1 PRIOR ART




FIG.2 PRIOR ART

11




FIG.3




FIG.4

14

DIR ENTRY TAG → POINTER TO LEADING FAT




FIG.5




FIG.6

24

DIR ENTRY TAG → POINTER TO LEADING FAT




FIG. 7




FIG.8

34




FIG.9




FIG.10




FIG.11




FIG. 12




FIG.13




FIG.14




FIG.15




FIG.16




FIG.17




FIG.18




FIG.19




FIG.20




FIG.21




FIG.22




FIG.23




FIG.24




FIG.25

